



GARY R. HERBERT  
Governor  
GREGORY S. BELL  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

### Inspection Report

### Minerals Regulatory Program

Date May 20, 2010

Reviewed:

<b>Mine Name:</b> Temple Strike	<b>Permit Number:</b> S/039/0015
<b>Operator Name:</b> Bill Day	<b>Inspection Date:</b> April 25, 2010
<b>Inspector(s):</b> John Rogers and Lynn Kunzler	<b>Time:</b> 2:30 PM – 3:30 PM
<b>Other Participants:</b> none	<b>Mine Status:</b> active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Roads (maintenance, surfacing, dust control, safety)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Reclamation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. Soils	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Revegetation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

**Bond Amount:** \$20,700.00, needs to be escalated to current status. The permit fees for 2009 have not been paid.

**Purpose of Inspection:** Routine inspection while in the area

**Inspection Summary:** Trash is scattered all over the area. This includes old dilapidated vehicles, equipment, tanks, tires, containers, an open bucket of oil, broken pallets, batteries and trailers on site that appear unusable. The site is in very poor condition. Drums are on site and are leaking fuel/solvent. It appears that there has been no recent mining and has been no attempt at reclamation or retention of topsoil.

**Conclusions and Recommendations:** I contacted Bill Day (operator) by telephone on May 4, 2010 and indicated to him the poor condition of the site. I gave him until May 14, 2010 to clean up the site or a violation would be issued. He indicated that he would do so. At this point in time (May 20, 2010) I have not inspected the site, but will do so when in the area. If no progress has been made a violation will be issued.

**Inspector's Signature**

JCR: vs

Bill Day – operator

O:\M039-Sanpete\S0390015-Templestrike\inspections\Insp-04262010.doc



Dilapidated equipment



Dilapidated equipment



Dilapidated structures



Old equipment



Trash



Quarry looking north



Quarry looking east



Trash / old equipment



Trash



Dilapidated equipment



Trash / barrels of solvent



Trash / open container of oil